



US ARMY CORPS  
OF ENGINEERS  
NEW ENGLAND DIVISION

## INVENTORY INSPECTION REPORT



---

# COLEBROOK LAKE SERVICE BRIDGE COLEBROOK LAKE DAM COLEBROOK, CT

MAY 1995

NEW ENGLAND DIVISION

# Lichtenstein

NEW YORK

NEW JERSEY

PENNSYLVANIA

MASSACHUSETTS

OHIO

CONNECTICUT

FLORIDA

ALABAMA

BRIDGES

HIGHWAYS

RAILROADS

SITE ENGINEERING

DAMS

## TABLE OF CONTENTS

	<u>PAGE</u>
I. INTRODUCTION	1
II. BRIDGE DESCRIPTION	1
III. INSPECTION PROCEDURE	1
IV. FRACTURE CRITICAL EVALUATION	1
V. SUMMARY OF INSPECTION	
A. Substructure	3
1) Abutment	3
2) Pier	3
3) Intake Control Tower (Exterior only)	4
B. Superstructure	4
1) Girders	4
2) Bearings	4
3) Cross Frames	4
4) Floor System Lateral Bracing	4
5) Deck/Curb	5
6) Expansion Joints	5
7) Paint	5
8) Miscellaneous	5
a. Light Standards	5
b. Utilities	6
c. Railings	6
d. Scuppers	6
e. End Posts	6
VI. PHOTOGRAPHS	7
VII. CONCLUSIONS AND RECOMMENDATIONS	13
VIII. FIELD NOTES	14
IX. RATING ANALYSIS (By Others)	
X. APPENDIX	A1

**I. INTRODUCTION**

**II. BRIDGE DESCRIPTION AND HISTORY**

**III. INSPECTION PROCEDURE**

**IV. FRACTURE CRITICAL EVALUATION**

## **I. INTRODUCTION**

The Colebrook River Service Bridge is located in Colebrook, Connecticut and provides access to the Intake Control Tower for the Colebrook River Dam. The structure was inspected on January 25, 1995.

## **II. BRIDGE DESCRIPTION**

The structure is a 268 foot two-span, two girder plate girder bridge supporting a 9 inch reinforced concrete deck (see Report Photo 1). Both spans are 133 feet 0 inches from centerline support to centerline support with 2 feet between centerline bearings at the pier. The simple span girders are supported by corbels on the Intake Control Tower at the west end, a reinforced concrete pier in the center and a reinforced concrete abutment at the east end. The distance centerline to centerline of girders is 9 feet 0 inches. The spacing of the cross frames, between girders, varies from 15 feet 9 inches to 18 feet 0 inches on center (see General Plan and Elevation, sheet 2). Utilities are suspended from the deck along the center and north side of the structure.



## **III. INSPECTION PROCEDURE**

The field inspection included a complete hands-on/visual inspection of all bridge components above ground and water level, excluding the interior of the Intake Control Tower. Special attention was given to fracture critical members. An underbridge inspection unit was utilized to access the underside of the superstructure and portions of the substructure (see Report Photo 2). All pertinent data concerning condition findings of the various bridge elements was recorded on field inspection forms. Color photographs (35mm) were taken and field sketches made to document the typical conditions of the structure as well as any deteriorated areas which deviated from the typical conditions. The complete set of field inspection notes are included in Section VIII - FIELD NOTES of this Report.

## **IV. FRACTURE CRITICAL EVALUATION**

A Fracture Critical Member (FCM) is a member in tension or with a tension element, whose failure would probably cause a portion of or the entire bridge to collapse. FCM's are subject to fracture due to brittle fracture or fatigue failure. Brittle fracture of a steel member can be caused by the sudden application of a load which causes high total stresses in the presence of a defect in the metal (i.e. nick, notch, crack) and is more likely to occur during cold weather when the steel tends to be more brittle. The formation of a fatigue crack in a steel member is caused by repeated cycles of stress due to live loads. The fatigue life of a steel bridge is dependent on the magnitude of the stress range and the fatigue strength of details. The fracture critical members on this bridge consist of the girders. The girders appear to be in good condition. Further testing does not appear necessary at this time although special attention should be given to these members in subsequent scheduled inspections.





DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
COLEBROOK RIVER SERVICE BRIDGE  
INVENTORY INSPECTION

## GENERAL PLAN AND ELEVATION

## Lichtenstein

**A.G. LICHTENSTEIN & ASSOCIATES, INC.**  
**CONSULTING ENGINEERS**

FILE: D:\COLEGPE.DWG

SCALE: N.T.S.

DATE: 5/95

## **V. SUMMARY OF INSPECTION**

## V. SUMMARY OF INSPECTION FINDINGS

The following pages provide a summary of typical conditions found with significant deviations from typical conditions noted. Cross references are made as required to Section VI. - Photographs of this Report which detail specific condition findings.

The evaluations (e.g. "satisfactory", "good", etc.) used in the text of the condition description are based upon the attached *FHWA Structure Inventory, Condition, and Appraisal Rating Guide* sheet included in the Appendix.

### A. Substructure

The bridge substructure was generally in good condition. Isolated locations of minor deterioration due to map cracking and spalling were present on the substructure elements.

The following is a summary of condition findings:

#### 1. Abutment: (GOOD CONDITION)

The abutment was generally in good condition. The following is a summary of condition findings:

- 2'-0" and 10" hairline cracks were noted on the backwall.
- The joint seal was partially missing between the breastwall and backwall.
- Rust stains on the backwall adjacent to the joint opening were observed.

#### 2. Pier: (GOOD CONDITION)

The pier was generally in good condition (see Report Photo 3). The following is a summary of condition findings:

- The pier exhibited 3 spalls, the largest being 4" long by 4" wide by up to 4" deep corner spall on the base.
- A 15" diameter delamination was noted near the base of the pier of the east face.
- Rust stains were observed near top of the pier.

3. Intake Control Tower (Exterior only): (GOOD CONDITION)

The Intake Control Tower was generally in good condition (see Report Photo 4) with isolated locations of exposed reinforcing on the walkway surrounding the tower (see Report Photo 5).

B. Superstructure

The bridge superstructure was generally in good condition (see Report Photo 6). Isolated locations of distress on the superstructure elements are noted as follows:

1. Girders: (GOOD CONDITION)

The girders were generally in good condition. No significant defects were observed.

2. Bearings: (SATISFACTORY CONDITION)

The bearings were generally in satisfactory condition. The following is a summary of condition findings:

- The expansion bearing anchor bolts were bent at the south expansion bearing at the abutment (1 out of 2), the south expansion bearing at the pier (2 out of 2), and the north expansion bearing at the pier (1 out of 2) (see Report Photo 7).
- A gap was observed between the anchor bolt nuts and the anchor bolts on the north fixed bearing at the pier (1 out of 2), the north expansion bearing at the pier (1 out of 2), and the north fixed bearing at the Intake Control Tower (1 out of 2) where the nut was found to be loose (see Report Photo 8).

3. Cross Frames: (GOOD CONDITION)

The cross frames between girders were generally in good condition with no defects observed (see Report Photo 9).

4. Floor System Lateral Bracing: (GOOD CONDITION)

The lateral bracing was generally in good condition with no significant defects observed.



5. Deck/Curb: (GOOD CONDITION)

The deck was generally in good condition with minor areas of concrete distress observed (see Report Photo 10). The following is a summary of the condition findings:

a. Span 1: Top of Deck

- A spall 9" long x 2" wide x up to 1/8" deep was noted at the north curbline (see Report Photo 11).
- Numerous hairline cracks were observed on the deck and curbs, the longest being 10'.

b. Span 2: Top of Deck

- Two minor spalls, up to 3/16" deep, were observed on the deck.
- The deck and curbs exhibited isolated hairline cracks.

c. Spans 1 and 2: Underside of Deck

- The underside of deck was generally in good condition with reinforcing chair rust stains. There were no stay-in-place forms present.

6. Expansion Joints: (SATISFACTORY CONDITION)

The expansion joints were generally in satisfactory condition with the joint sealer partially separated from the expansion plates at both expansion joints (see Report Photo 12).

7. Paint: (GOOD CONDITION)

The paint on the bridge was generally in good condition with no significant problems observed.

8. Miscellaneous:

a. Light Standards: (GOOD CONDITION)

The light standards on the bridge were generally in good condition. No significant defects were observed.

b. Utilities: (GOOD CONDITION)

The utilities on the bridge were in good condition. No defects were observed.

c. Railings: (GOOD CONDITION)

The railings were generally in good condition. No significant defects were observed.

d. Scuppers: (GOOD CONDITION)

The scuppers were generally in good condition. No significant defects were observed.

e. End Posts: (GOOD CONDITION)

The end posts were generally in good condition with an isolated 8" long x 4" wide x up to 3/4" deep corner spall observed at the northeast corner of the south end post.

## **VI. PHOTOGRAPHS**

**Lichtenstein**

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

INVENTORY INSPECTION OF THE  
COLEBROOK LAKE SERVICE BRIDGE

COLEBROOK LAKE DAM – COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784

PHOTO NO.

①



DESCRIPTION: SOUTH ELEVATION OF BRIDGE.

PHOTO NO.

②



DESCRIPTION: TYPICAL PROCEDURE FOR CLOSE-UP INSPECTION OF  
SUPERSTRUCTURE.



**Lichtenstein**

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

# INVENTORY INSPECTION OF THE COLEBROOK LAKE SERVICE BRIDGE

COLEBROOK LAKE DAM – COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784



PHOTO NO.

③



PHOTO NO.

④

DESCRIPTION: EAST ELEVATION OF PIER.

DESCRIPTION: EAST ELEVATION OF INTAKE CONTROL TOWER.



**Lichtenstein**

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

INVENTORY INSPECTION OF THE  
COLEBROOK LAKE SERVICE BRIDGE

COLEBROOK LAKE DAM – COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784

PHOTO NO.

5



PHOTO NO.

6



DESCRIPTION: EXPOSED REINFORCING ON WALKWAY SURROUNDING THE  
INTAKE CONTROL TOWER.

DESCRIPTION: SUPERSTRUCTURE FRAMING LOOKING WEST.



**Lichtenstein**

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

INVENTORY INSPECTION OF THE  
COLEBROOK LAKE SERVICE BRIDGE

COLEBROOK LAKE DAM – COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784

PHOTO NO.

7



DESCRIPTION: NORTH ELEVATION OF NORTH EXPANSION BEARING ON PIER. NOTE BENT ANCHOR BOLT.

PHOTO NO.

8



DESCRIPTION: NORTH ELEVATION OF NORTH FIXED BEARING ON INTAKE CONTROL TOWER. NOTE GAP BETWEEN ANCHOR BOLT NUT AND ANCHOR BOLT.



# Lichtenstein

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

## INVENTORY INSPECTION OF THE COLEBROOK LAKE SERVICE BRIDGE


COLEBROOK LAKE DAM - COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784

PHOTO NO.

9



DESCRIPTION: TYPICAL GIRDER TO CROSS FRAME LOWER WELDED CONNECTION.

PHOTO NO.

10



DESCRIPTION: BRIDGE DECK LOOKING EAST.



**Lichtenstein**

A.G. LICHTENSTEIN & ASSOCIATES, INC.  
CONSULTING ENGINEERS

INVENTORY INSPECTION OF THE  
COLEBROOK LAKE SERVICE BRIDGE

COLEBROOK LAKE DAM – COLEBROOK, CT

DATE: MAY, 1995

PROJECT: 1784

PHOTO NO.

(11)



DESCRIPTION: MINOR SPALL IN CONCRETE DECK AT NORTH CURB LINE.

PHOTO NO.

(12)



DESCRIPTION: EXPANSION JOINT AT PIER LOOKING SOUTH. NOTE JOINT SEALER PARTIALLY SEPARATED FROM EXPANSION PLATES.

## **VII. CONCLUSIONS AND RECOMMENDATIONS**

## VII. CONCLUSIONS AND RECOMMENDATIONS

Based upon the results of the 1995 Inventory Inspection, the Colebrook River Service Bridge is in overall good condition. Isolated locations of satisfactory condition are present on the structure. The following is a list of recommendations:

1. The anchor bolts at the expansion bearings (4 locations) appear to be "bent" toward the contracted position. Based upon our observation, an investigation should be performed to determine the cause of this condition and whether or not the "bent" anchor bolts should be replaced. Our cost estimate is based on replacement of these anchor bolts which would require jacking the existing structure.
2. The anchor bolt nuts at the fixed bearings (2 locations) should be tightened. The nut at the expansion bearing anchor bolt (1 location) should be secured.
3. The joint seal between the breastwall and backwall is partially missing and should be replaced with new joint filler to prevent water runoff onto the abutment seat.
4. The joint sealer at both expansion joints is partially separated from the expansion plates apparently due to the normal expansion and contraction of the joints. The joint sealer should be removed and replaced with new joint sealer to prevent water runoff through the joint.

<u>Description</u>	<u>Estimated Construction Cost</u>
a. Remove and replace bent anchor bolts at expansion bearings (4 locations).	\$20,000.
b. Tighten anchor bolt nuts at fixed bearings (2 locations). Secure nut at expansion bearing (1 location).	\$ 500.
c. Remove and replace joint filler between breastwall and abutment backwall.	\$ 1,000.
d. Remove and replace joint sealer at both expansion joints.	\$ 500.
e. Continue regular maintenance schedule.	—

## **VIII. FIELD NOTES**




TEMP = 30° F

JOINT OPENING

TOWER (FIXED) = 1 1/2" N ↑

PIER (EXP.) = 3 1/8"



LEGEND:

} HAIRLINE CRACK

⊗ SPALL

■ - SCUPPER

TOP OF DECK

NOTES: NOTE: ≈ 25% OF DECK COVERED W/ SNOW + ICE [2-3]

- CONCRETE DECK

- ALL SCUPPERS CLEAR & FUNCTIONING

① SEAL AT JOINT BEGINNING TO FAIL,  
MEMBRANE PULLING AWAY FROM STEEL [2-6]

NOTE: SEVERAL LIGHT SURFACE SCRAPS ON DECK, APPARENTLY FROM SNOW PLOW

DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM

SERVICE BRIDGE

NOTES BY:

LICHTENSTEIN

CONSULTING ENGINEERS

JOB #1784


DATE: 1/25/95

CREW: [unclear]

SHEET 1 OF 7

TEMP = 30°F

DECK JOINT OPENING  
ABUT (EXP.) = 2 3/8"



LEGEND:

- { HARLINE CRACK
- ⊗ SPALL

NOTES: ① 1 1/2" Ø x 3/16" DEEP SPALL

② UP TO 3" LONG SECTIONS OF JOINT SEAL PULLING AWAY FROM

STEEL 2-8,9

③ 2" x 1" x 1/4" DEEP SPALL

Top of Deck


DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/25

CREW: RWH, B, BH SHEET 2 OF 7




NOTES: Typ. Conditions: - All framing o.k. except as noted on  
 North Girder Elev. sheet, Span 2 (Sht. 7 of 17)  
 - Underside of deck displays chair rust staining  
 otherwise in good condition

DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION CORPS OF ENGINEERS  
 COLEBROOK RIVER DAM  
 SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
 CONSULTING ENGINEERS

JOB #1784      DATE: 1/25/25  
 CREW: BH, PWN, PG      SHEET 3 OF 7



NOTES: Typ. Cond. - All Framing O.K.

- Underside of deck displays chair rust stains, otherwise in good condition.

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS


COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95

CREW: BH, PWN, PG SHEET 4 OF 17

↑ N



FRAMING PLAN

9'-0" CC  
 6 1/4"  
 4" t = 1 1/2"  
 T-section  
 Typical

NOTES:


DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION CORPS OF ENGINEERS  
 COLEBROOK RIVER DAM  
 SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
 CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/85  
 CREW: BH, PM, PG SHEET 5 OF 17

5  
 17


18



$\angle 5 \times 5 \times \frac{3}{8}$ "  
 TYPICAL SECTION

$\times 4 \times 3 \frac{1}{8}$ "  
 $6 \times \frac{3}{8}$ " stiff. p.  
 @ intermediate  
 diaph. only

Section @ Support  
 is similar except  
 top Lateral member  
 is channel  $\rightarrow$



17  
 6

19

NOTES:

DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION CORPS OF ENGINEERS  
 COLEBROOK RIVER DAM  
 SERVICE BRIDGE


NOTES BY: LICHTENSTEIN  
 CONSULTING ENGINEERS

JOB #1784      DATE: 1/25/75

CREW: BM, R, PHN      SHEET 6 OF 17



West



NORTH GIRDER ELEVATION  
SPAN 2

NOTES:


① Bot. of bow 1/8" ↓ over 10" span. (Tension E) 1-9

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS  
COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784	DATE: 1/25/95
CREW: BH, AB, PWN	SHEET 7 OF 17

8  
17  
21



NOTES: (1) SPALL ON ENDOPOST 9" x 4" x 3/8" HIT ? [2-10]

(2) JOINT FILLER MISSING - FALLING OUT

(3) STAINS ON BACKWALL FROM WATER THROUGH JOINT

(4) HAIRLINE CRACK 2' LONG

(5) FROM UTILITY SLOTTED 10" LONG

(6) ICB ON BACKWALL (NORTH SIDE) [2-14]

DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM

SERVICE BRIDGE

NOTES BY: LICHTENSTEIN

CONSULTING ENGINEERS


JOB #1784

DATE: 1/25/95


CREW: PG, AM, OM

SHEET 8 OF 17

BRIDGE ELEVATION



SOUTH ELEVATION



SPALLING

NOTES: ① 15"  $\phi$  HOLLOW [5-15]

② 4" X 3" X 1" DEEP SPALL

③ 4" X 1/2" DEEP SPALL

WATER STAINING AT TOP OF PIER

PIER

DEPARTMENT OF THE ARMY

NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM

SERVICE BRIDGE

NOTES BY: LICHTENSTEIN

CONSULTING ENGINEERS

JOB #1784

DATE: 1/25/95

CREW: PC, EM, PWN


SHEET 9 OF 17

9  
17

22


ELEVATION

WEST



ELEVATION

NORTH



NOTES:

① 4" x 4" x 4" CORNER SPALL  
 Top of Pier Cap O.K.

PIER


DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION CORPS OF ENGINEERS  
 COLEBROOK RIVER DAM  
 SERVICE BRIDGE

NOTES BY: UCHTENSTEIN  
 CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95

CREW: PAN, B, RG SHEET 10 OF 17





NOTES: ① EXPOSED REINF — NO COVER ON <sup>Top of</sup> SOUTH SIDE WALKWAY  
DECK SLAB 2-20

NOTE: INSPECTION OF TOWER WAS LIMITED TO  
EAST FACE OF TOWER



INTAKE CONTROL  
TOWER

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784	DATE: 1/25/95
CREW: FUN, BH, PC	SHEET 11 OF 17



NORTH EXPANSION BEARING C ABUTMENT

TEMP. = 30°F



NOTES:

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS  
COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95

CREW: RUN, PG, OH SHEET 12 OF 17





SOUTH EXPANSION BEARING @ ABUTMENT

TEMP - 30° F

NOTES: ① BENT BOLT (Bent west) (S. Anchor Bolt) OUTSIDE OF SOUTH GIRDER AT ABUTMENT [2-13]  
 DIMENSIONS ON EAST SIDE

DEPARTMENT OF THE ARMY  
 NEW ENGLAND DIVISION CORPS OF ENGINEERS  
 COLEBROOK RIVER DAM  
 SERVICE BRIDGE  
 NOTES BY: LICHTENSTEIN  
 CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95  
 CREW: PG, PNH, BH SHEET 13 OF 17



NORTH FIXED BEARING @ PIER

SOUTH <sup>FIXED</sup> BRG. O.K @ PIER

NOTES:

① North anchor bolt nut unthreaded to top of bolt



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784	DATE: 1-25-85
CREW: BA, PN, RG	SHEET 14 OF 17





SOUTH EXPANSION BEARING @ PIER

TEMP = 30°F

NOTES:

① North-South Anchor Bolt slightly bent west

Signs of movement not apparent, paint sealed.



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95

CREW: BM, P.W., PG SHEET 15 OF 17



NORTH EXPANSION BEARING @ PIER

TEMP. 30°F

NOTES:

① North Anchor bolt bent <sup>11-14</sup> West, South anchor bolt nut not threaded all the way down.

Signs of movement not apparent (paint sealed)



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/95

CREW: BH, DM, PG SHEET 16 OF 17



NORTH FIXED BEARING @ CONTROL TOWER

SOUTH BRG. O.K. @ CONTROL TOWER

NOTES:

① North Anchor Bolt not loose and almost threaded off [1-20]

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION CORPS OF ENGINEERS

COLEBROOK RIVER DAM  
SERVICE BRIDGE

NOTES BY: LICHTENSTEIN  
CONSULTING ENGINEERS

JOB #1784 DATE: 1/25/25

CREW: TUN, BN, PG SHEET 17 OF 17

**IX. RATING ANALYSIS**  
**(By Others)**

# Service Bridge Rating Analysis

Black Rock Service Bridge (COLEBROOK RIVER LAKE SERVICE BRIDGE)  
Black Rock Dam IDENTICAL TO BLACK ROCK LAKE  
Thomaston CT SERVICE BRIDGE)

3 May 1994

Vehicle: HS-20

## Rating Summary:

	Inventory	Operating
Deck	19.0	31.6
Girder midsection	21.6	53.1
Girder 1st cutoff	27.4	55.3
Girder 2nd cutoff	31.4	62.0

## Rating:

Inventory	19.0 T
Operating	31.6 T




SUBJECT BLANK ROCK SERVICE BRIDGE

COMPUTATION BRIDGE RATING ANALYSIS

COMPUTED BY M.D.

CHECKED BY

DATE 5-29-44



### DECK RATING

GR 40 REINFORCING STEEL

$$M_u = \phi M_n$$

$$= \phi (A_s f_s) \left( d - \frac{a}{2} \right)$$

$$= 0.9 (1.62 \times 40) \left( 6.49 - \frac{8}{2} \right)$$

$$= 140 \text{ K.in}$$

$$M_u = 11.7 \text{ K.ft}$$

$$a = \frac{A_s f_s}{0.85 f'_c b} = \frac{1.62(40)}{0.85(3)(12)} = 0.81$$

$$d = 8\frac{1}{2} - 1\frac{1}{2} \cdot \frac{5}{16} = 6.69$$

### DEAD LOAD MOMENT CALCULATION

$$Q = \left( \frac{8\frac{1}{2}}{12} \right) \times 1 \times 15 = 0.11 \text{ K/ft}$$

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 2SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION RATING ANALYSISCOMPUTED BY UD

CHECKED BY \_\_\_\_\_


DATE 5-2-94

REACTION @ GIRDER.

$$\text{DECK } \frac{14.25(0.11)}{2} = 0.784 \text{ k.}$$

$$\text{RAILWAY + CURBS} = \underline{0.16 \text{ k.}}$$

$$0.94 \text{ k.}$$



$$M_G = -0.16(7.125) - 0.78(3.56) + 0.94(4.5)$$

$$= -1.14 - 2.78 + 4.23$$

$$= 0.31 \text{ k.ft.}$$

$$M_{uG} = \left(\frac{C+2}{32}\right)16 = \left(\frac{C+2}{32}\right)16 = 5.5 \text{ k.ft.}$$

RATING.

INVENTORY:

$$M_U = 1.3[D + \frac{5}{8}RF(L+I)] \quad \text{ASSUME IMPACT IS 0}$$

$$11.7 = 1.3[0.31 + \frac{5}{8}RF(5.5)]$$

$$RF = 0.95$$

$$\text{RATING} = (0.95 \times 20) = \underline{19.0T}$$

OPERATING

$$11.7 = 1.3[0.31 + RF(5.5)]$$

$$RF = 1.58$$

$$\text{RATING} = (1.58 \times 20) = \underline{31.6T}$$

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 3

SUBJECT BLACK ROCK SERVICE BRIDGE

COMPUTATION BRIDGE RATING ANALYSIS


COMPUTED BY N.D.

CHECKED BY \_\_\_\_\_

DATE 5-2-54


# ANALYSIS OF LOADING IN BEAMS

## ANALYSIS BY HS-20 TRUCK LOAD.



$$R_A = \frac{W(2.5) + 8.5(W)}{9} = 1.22W$$

$$DF = 1.22 \times \text{WHEEL LOAD} = 0.61 \times \text{TRUCK LOAD}$$



$$R_A = \frac{5.5}{4} = 0.61 \times \text{LANE LOAD}$$

TRUCK LOAD WILL GOVERN.

TRUCK LOAD @ MIDSPAN.

$$\text{LOAD ON BEAM} = 2116.9 \times .61 = 1291.3 \text{ K.Ft}$$

PROJECT: BLACK ROCK LAKE  
TITLE: SERVICE BRIDGE  
DATE: 02-May-94

HS-20 LOADING MOMENTS  
WITH LOADING AT ANY POINT

X DIST = THE DISTANCE OF THE CENTER AXLE FROM THE END OF SPAN

CLEAR SPAN 133 ft

SPAN	133	LANE @ MID	HS-20 @ MID
HS-20 LOADING		2013.6	2116.9

LOCATION	X DIST	LANE LOAD AT X	HS-20 AT X
MOMENT AT X1	66.50	2013.6	2114.0
MOMENT AT X2	34.00	1532.7	1624.3
MOMENT AT X3	20.50	1050.1	1084.7
MOMENT AT X4	0.00	0.0	0.0

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 5

SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY M.D.

CHECKED BY \_\_\_\_\_

DATE 5/2/54

## DEAD LOAD ON GIRDERS.

GIRDERS.	TOP FLANGE	68.1 lb/ft
	WEB	99.6 lb/ft
	BOT FLANGE	95.3 lb/ft
		<hr/> 263 lb/ft

$$\text{DECK} = 14'3" \times 8\frac{1}{2}"/2 = 757 \text{ lb/ft}$$

$$\text{STIFFENERS} = 15 \text{ lb/ft}$$

$$\text{WIND BRACING} \quad \text{Base @} \quad 3 \text{ lb/ft}$$


---


$$1.04 \text{ k/ft}$$

$$M_D = \frac{(1.04)(133)^2}{8} = 2299.6 \text{ k}\cdot\text{ft}$$

## SUPERIMPOSED D

$$\begin{aligned} \text{CURB. } (12/12)(13.5/12)(.150) &= 0.14 \text{ k/ft} \\ \text{RAILING } 15 \text{ lb/ft} &= 0.015 \\ \hline &= 0.155 \text{ k/ft} \\ &= 0.16 \text{ k/ft.} \end{aligned}$$


$$M_{SD} = \frac{(0.16)(133)^2}{8} = 353.8 \text{ k}\cdot\text{ft}$$

27 Sept 49

CORPS OF ENGINEERS, U. S. ARMY

PAGE 6SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY M.D. CHECKED BY \_\_\_\_\_ DATE 5/2/94

## SECTION PROPERTIES OF GIRDER @ M.D. SPAN.



EFFECTIVE FLANGE

thickness = 8"

width =  $b_f = \frac{S}{2} = 4' = 48''$  $b(s) = 48''$ DIST FROM CORN. TO  $Q_L$  LINE =  $2'6.25''$   
= 31.5" $b_f = 48'' + 31.5'' = 79.5''$  $n = 9$  FOR LIVE LOAD $n = 9(3) = 27$  FOR SUPERIMPOSED  $D_L$ SECTION PROPERTIES -  $in^4$ 

SEE ATTACHED SPREADSHEET

	$D_L$	SUPERIMPOSED $D_L$ $n=27$	$LL$ $n=9$
$S_{concrete}$	0	3233	6005
$S_{top}$	2011	3886	7856
$S_{bot}$	2445	2727	2909



**SERVICE BRIDGE RATING ANALYSIS**  
**PLATE GIRDER COMPOSITE SECTION PROPERTIES**

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/02/94  
 SECTION: MIDSPAN

SECTION PROPERTIES: CONCRETE	
EFFECTIVE FLANGE bf	79.5
N	9
SLAB THICKNESS	8

GEOMETRY:		
MEMBER	WIDTH	HEIGHT
TOP FLANGE	16	1.25
WEB	0.375	78
BOT FLANGE	16	1.75

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		3233	6005
S top flange	2011	3886	7856
S bot flange	2445	2727	2909

**COMPOSITE STEEL:**

SECTION	AREA	Y	AY	lc	AY^2	lb
BOT FL	28	0.875	25	7	21	29
WEB	29.25	40.75	1192	14830	48571	63401
TOP FL	20	80.375	1608	3	129203	129205

Y 36.56 in  
 AY^2 103255 in^4  
 lc 89380 in^4

S top 2011 in^3  
 S bot 2445 in^3

**COMPOSITE SECTION: LONG TERM WITH CREEP  $N_{eff} = N^*3$**

SECTION	AREA	Y	AY	lc	AY^2	lb
STEEL	77.25	36.6	2824	89380	103255	192635
CONCRETE	23.6	83.8	1977	126	165532	165658

Y 47.60 in  
 AY^2 228502 in^4  
 lc 129791 in^4

S con 3233 in^3  
 S top 3886 in^3  
 S bot 2727 in^3

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE SECTION PROPERTIES

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/02/94  
 SECTION: MIDSPAN

COMPOSITE SECTION: LIVE LOAD - NO CREEP  $N_{eff} = N$

SECTION	AREA	Y	AY	Ic	AY <sup>2</sup>	Ib
STEEL	77.25	36.6	2824	89380	103255	.192635
CONCRETE	70.7	83.8	5921	377	495894	496271

Y 59.11 in  
 AY<sup>2</sup> 516936 in<sup>4</sup>  
 Ic 171970 in<sup>4</sup>

S con 6005 in<sup>3</sup>  
 S top 7856 in<sup>3</sup>  
 S bot 2909 in<sup>3</sup>

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 10

SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY M.D.

CHECKED BY \_\_\_\_\_

DATE 5-2-54

$$M_L = (2116.9 \times .61) = 1291.3 \text{ k.f.}$$

$$\text{INVENTORY RATING} = \left( \frac{1682.4}{1291.3} \right)_{20} = \boxed{26.17}$$

OPERATING.

$$f_{s \text{ bot}} = 27 - 11.3 - 1.5L = 14.14 \text{ ksi}$$

$$\text{AVAIL } M_L = 14.14 (2909) / 12 = 3427.8 \text{ k.f.}$$

$$\text{OPERATING RATING} = \left( \frac{3427.8}{1291.3} \right)_{20} = \boxed{53.17}$$

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 9.

SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE BENT ANALYSISCOMPUTED BY M.D.

CHECKED BY \_\_\_\_\_

DATE 5/2/54

DEAD LOAD NO COMPOSITE ACTION

$$f_{s \text{ top}} = \frac{M}{S} = \frac{2299.6(12)}{2011} = 13.7 \text{ ksi}$$

$$f_{s \text{ bot}} = \frac{M}{S} = \frac{2299.6(12)}{2045} = 11.3 \text{ ksi}$$

SUPERIMPOSED Q

$$f_{s \text{ comp}} = \frac{M}{S} = \frac{353.8(12)}{3233(27)} = 0.05 \text{ ksi}$$

$$f_{s \text{ top}} = \frac{M}{S} = \frac{353.8(12)}{3886} = 1.10 \text{ ksi}$$

$$f_{s \text{ bot}} = \frac{M}{S} = \frac{353.8(12)}{2727} = 1.56 \text{ ksi}$$

ALLOW STRESS FOR LIVE LOAD

$$f_{s \text{ comp}} = 1.2 - 0.05 = 1.15 \text{ ksi}$$

$$f_{s \text{ top}} = 19.8 - 13.7 - 1.1 = 5.0 \text{ ksi}$$

$$f_{s \text{ bot}} = 19.8 - 11.3 - 1.56 = 6.94 \text{ ksi}$$

$$M_{max} = f_{s \text{ comp}} S : 5179.3 \text{ k.ft}$$

$$f_{s \text{ top}} S : 3273.3 \text{ k.ft}$$

$$f_{s \text{ bot}} S : 1682.4 \text{ k.ft}$$

**SERVICE BRIDGE RATING ANALYSIS**  
**PLATE GIRDER COMPOSITE RATING**

PROJECT: Black Rock Service Bridge  
DATE: 05/02/94  
SECTION: Mid-Span

RATING	
INVENTORY	26.1 Tons
OPERATING	53.1 Tons

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		3233	6005
S top flange	2011	3886	7856
S bot flange	2445	2727	2909

OTHER	
Fy STEEL	36000
fc CONCRETE	3000
n	9
ALLOW fs INVENTORY	19800
ALLOW fs OPERATING	27000
ALLOW fc	1200
DISTRIBUTION FACTOR	0.61

MOMENTS k-ft	
DEAD LOAD	2300
SUPERIMPOSED DL	354
LIVE LOAD	2117

DEAD LOAD STRESS	fs top	13.72 ksi
	fs bot	11.29 ksi
SUPERIMPOSED	fc conc	0.05 ksi
DEAD LOAD STRESS	fs top	1.09 ksi
	fs bot	1.56 ksi
AVAILABLE STRESSES	fc conc	1.15 ksi
FOR LIVE LOAD	fs top	4.99 ksi
(INVENTORY)	fs bot	6.95 ksi
AVAILABLE STRESSES	fc conc	1.15 ksi
FOR LIVE LOAD	fs top	12.19 ksi
(OPERATING)	fs bot	14.15 ksi

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE RATING

PROJECT: Black Rock Service Bridge  
DATE: 05/02/94  
SECTION: Mid-Span

AVAILABLE LIVE LOAD	M conc	5179 k-ft
MOMENT	Ms top	3267 k-ft
(INVENTORY)	Ms bot	1685 k-ft

AVAILABLE LIVE LOAD	M conc	5179 k-ft
MOMENT	Ms top	7980 k-ft
(OPERATING)	Ms bot	3430 k-ft

CONTROLLING VALUES		
(INVENTORY)	M max.	1685 k-ft
(OPERATING)	M max.	3430 k-ft



27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 13

SUBJECT BLACK ROCK BRIDGE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY N.D.

CHECKED BY


DATE

5-2-94

## ANALYSE BRIDGE CAPACITY AT CUTOFFS

## CUTOFF SECTION:

## MEMBER PROPERTIES



## SECTION PROPERTIES

	STEEL ONLY	COMPOSITE W. GROSS	COMPOSITE W/OUT CREEP
$S_{\text{GROSS}}$		2856	2474
$S_{\text{TOP}}$	1668	3514	7510
$S_{\text{BOT}}$	1874	2142	2301

DEAD MOMENT @ 1ST CUTOFF 34' FROM END

$$D = 1.04 \text{ k/ft.}$$

$$SD = 0.16 \text{ k/ft}$$

$$M_D = \frac{1.04 (34)}{2} (133 - 34) = 1750.3 \text{ k.ft}$$

$$M_{SD} = \frac{0.16 (34)}{2} (133 - 34) = 269.3 \text{ k.ft}$$

$$M_L = 1624.3 \text{ k.ft.} \times 0.61 = 990 \text{ k.ft}$$

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE SECTION PROPERTIES

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/03/94  
 SECTION: FIST CUTOFF AT 34' FROM END

SECTION PROPERTIES: CONCRETE	
EFFECTIVE FLANGE bf	79.5
N	9
SLAB THICKNESS	8

GEOMETRY:		
MEMBER	WIDTH	HEIGHT
TOP FLANGE	16	1
WEB	0.375	78
BOT FLANGE	16	1.25

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		2856	5474
S top flange	1668	3514	7510
S bot flange	1874	2142	2301

COMPOSITE STEEL:

SECTION	AREA	Y	AY	Ic	AY^2	Ib
BOT FL	.20	0.625	13	3	8	10
WEB	29.25	40.25	1177	14830	47387	62217
TOP FL	16	79.75	1276	1	101761	101762

Y 37.79 in  
 AY^2 93182 in^4  
 Ic 70807 in^4

S top 1668 in^3  
 S bot 1874 in^3

COMPOSITE SECTION: LONG TERM WITH CREEP  $N_{eff} = N \cdot 3$

SECTION	AREA	Y	AY	Ic	AY^2	Ib
STEEL	65.25	37.8	2466	70807	93182	163989
CONCRETE	23.6	83.3	1965	126	163561	163687

Y 49.86 in  
 AY^2 220883 in^4  
 Ic 106793 in^4

**SERVICE BRIDGE RATING ANALYSIS**  
**PLATE GIRDER COMPOSITE SECTION PROPERTIES**

PROJECT: BLACK ROCK SERVICE BRIDGE  
DATE: 05/03/94  
SECTION: FIST CUTOFF AT 34' FROM END

SECTION PROPERTIES: CONCRETE	
EFFECTIVE FLANGE bf	79.5
N	9
SLAB THICKNESS	8

GEOMETRY:		
MEMBER	WIDTH	HEIGHT
TOP FLANGE	16	1
WEB	0.375	78
BOT FLANGE	16	1.25

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		2856	5474
S top flange	1668	3514	7510
S bot flange	1874	2142	2301

**COMPOSITE STEEL:**

SECTION	AREA	Y	AY	Ic	AY^2	Ib
BOT FL	20	0.625	13	3	8	10
WEB	29.25	40.25	1177	14830	47387	62217
TOP FL	16	79.75	1276	1	101761	101762

Y 37.79 in  
AY^2 93182 in^4  
Ic 70807 in^4

S top 1668 in^3  
S bot 1874 in^3

**COMPOSITE SECTION: LONG TERM WITH CREEP  $N_{eff} = N^*3$**

SECTION	AREA	Y	AY	Ic	AY^2	Ib
STEEL	65.25	37.8	2466	70807	93182	163989
CONCRETE	23.6	83.3	1965	126	163561	163687

Y 49.86 in  
AY^2 220883 in^4  
Ic 106793 in^4

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE SECTION PROPERTIES

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/03/94  
 SECTION: FIST CUTOFF AT 34' FROM END

S con 2856 in<sup>3</sup>  
 S top 3514 in<sup>3</sup>  
 S bot 2142 in<sup>3</sup>

COMPOSITE SECTION: LIVE LOAD - NO CREEP Neff= N

SECTION	AREA	Y	AY	Ic	AY <sup>2</sup>	Ib
STEEL	65.25	37.8	2466	70807	93182	163989
CONCRETE	70.7	83.3	5886	.377	489991	490368

Y 61.43 in  
 AY<sup>2</sup> 513027 in<sup>4</sup>  
 Ic 141330 in<sup>4</sup>  
  
 S con 5474 in<sup>3</sup>  
 S top 7510 in<sup>3</sup>  
 S bot 2301 in<sup>3</sup>

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 11SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE EXISTING ANALYSISCOMPUTED BY N. D.

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_

## DEAD LOAD STRESS

$$f_D = \frac{M}{S}$$

$$f_{top} = \frac{(1750.3 \times 12)}{1668} = 12.59 \text{ ksi}$$

$$f_{bot} = \frac{(1750.3 \times 12)}{1874} = 11.21 \text{ ksi}$$

## SUPERIMPOSED D STRESS

$$f_D = M/S$$

$$f_{tens} = \frac{269.3(12)}{(2856 \times 27)} = 0.04 \text{ ksi}$$

$$f_{top} = \frac{269.3(12)}{3514} = 0.92 \text{ ksi}$$

$$f_{bot} = \frac{269.3(12)}{3122} = 1.01 \text{ ksi}$$

## STRESS AVAILABLE FOR LIVE LOAD (CONCRETE)

$$f_{tens} = 1.2 - 0.04 = 1.16 \text{ ksi}$$

$$f_{top} = 19.8 - 12.59 - 0.92 = 6.29 \text{ ksi}$$

$$f_{bot} = 19.8 - 11.21 - 1.01 = 7.08 \text{ ksi}$$

## AVAL LL MOM (CONCRETE)

$$M_{tens} = \frac{1.16(5474)(9)}{12} = 4762.4 \text{ k.ft}$$

$$M_{top} = \frac{6.29(7510)}{12} = 3936.5 \text{ k.ft}$$

$$M_{bot} = \frac{7.08(2701)}{12} = 1357.6 \text{ k.ft} \leftarrow \text{CONTROLS.}$$

**SERVICE BRIDGE RATING ANALYSIS**  
**PLATE GIRDER COMPOSITE RATING**

PROJECT: Black Rock Service Bridge  
 DATE: 05/03/94  
 SECTION: First cutoff at 34' from end

RATING	
INVENTORY	27.4 Tons
OPERATING	55.3 Tons

MOMENTS k-ft	
DEAD LOAD	1750
SUPERIMPOSED DL	269
LIVE LOAD	1624

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		2856	5474
S top flange	1668	3514	7510
S bot flange	1874	2142	2301

OTHER	
Fy STEEL	36000
f'c CONCRETE	3000
n	9
ALLOW fs INVENTORY	19800
ALLOW fs OPERATING	27000
ALLOW fc	1200
DISTRIBUTION FACTOR	0.61

DEAD LOAD STRESS	fs top	12.59 ksi
	fs bot	11.21 ksi
SUPERIMPOSED	fc conc	0.04 ksi
DEAD LOAD STRESS	fs top	0.92 ksi
	fs bot	1.51 ksi
AVAILABLE STRESSES	fc conc	1.16 ksi
FOR LIVE LOAD	fs top	6.29 ksi
(INVENTORY)	fs bot	7.08 ksi
AVAILABLE STRESSES	fc conc	1.16 ksi

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE RATING

PROJECT: Black Rock Service Bridge  
DATE: 05/03/94  
SECTION: First cutoff at 34' from end

FOR LIVE LOAD	fs top	13.49 ksi
(OPERATING)	fs bot	14.28 ksi

AVAILABLE LIVE LOAD	M conc	4762 k-ft
MOMENT	Ms top	3936 k-ft
(INVENTORY)	Ms bot	1358 k-ft

AVAILABLE LIVE LOAD	M conc	4762 k-ft
MOMENT	Ms top	8442 k-ft
(OPERATING)	Ms bot	2738 k-ft

CONTROLLING VALUES		
(INVENTORY)	M max.	1358 k-ft
(OPERATING)	M max.	2738 k-ft



27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 20

SUBJECT BLANK ROCK SERVICE BRIDGE


COMPUTATION BRIDGE RATING ANALYSIS

COMPUTED BY W.D.

CHECKED BY \_\_\_\_\_

DATE 5/3/99

# SECTION PROPERTIES @ END WTOFF



## SECTION PROPERTIES

	STEEL ONLY	COMPOSITE W/ CREEP	COMPOSITE W/OUT CREEP
$S_{x_{max}}$		2439	4830
$S_{x_{min}}$	1309	3105	7131
$S_{x_{net}}$	1309	1557	1688

## $P_{MON}$ @ 20.5' WTOFF

$$D = 1.04 \text{ K/Ft}$$

$$S_D = 0.16 \text{ K/Ft}$$

$$M_D = \frac{1.04(20.5)(133 - 20.5)}{2} = 1199.3$$

$$M_{SD} = \frac{0.16(20.5)(133 - 20.5)}{2} = 184.5$$

$$M_U = 1084.7 \times 0.61 = 661.7$$

**SERVICE BRIDGE RATING ANALYSIS**  
**PLATE GIRDER COMPOSITE SECTION PROPERTIES**

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/03/94  
 SECTION: SECOND CUTOFF AT 20.5' FROM END

SECTION PROPERTIES: CONCRETE	
EFFECTIVE FLANGE bf	79.5
N	9
SLAB THICKNESS	8

GEOMETRY:		
MEMBER	WIDTH	HEIGHT
TOP FLANGE	16	0.75
WEB	0.375	78
BOT FLANGE	16	0.75

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		2439	4830
S top flange	1309	3105	7131
S bot flange	1309	1557	1688

**COMPOSITE STEEL:**

SECTION	AREA	Y	AY	lc	AY^2	lb
BOT FL	12	0.375	5	1	2	2
WEB	29.25	39.75	1163	14830	46217	61047
TOP FL	12	79.125	950	1	75129	75130

Y 39.75 in  
 AY^2 84138 in^4  
 lc 52040 in^4

S top 1309 in^3  
 S bot 1309 in^3

**COMPOSITE SECTION: LONG TERM WITH CREEP  $N_{eff} = N^3$**

SECTION	AREA	Y	AY	lc	AY^2	lb
STEEL	53.25	39.8	2117	52040	84138	136179
CONCRETE	23.6	82.8	1953	126	161602	161728

Y 52.95 in  
 AY^2 215465 in^4  
 lc 82442 in^4

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE SECTION PROPERTIES

PROJECT: BLACK ROCK SERVICE BRIDGE  
 DATE: 05/03/94  
 SECTION: SECOND CUTOFF AT 20.5' FROM END

S con 2439 in<sup>3</sup>  
 S top 3105 in<sup>3</sup>  
 S bot 1557 in<sup>3</sup>

COMPOSITE SECTION: LIVE LOAD - NO CREEP Neff= N

SECTION	AREA	Y	AY	lc	AY <sup>2</sup>	lb
STEEL	53.25	39.8	2117	52040	84138	136179
CONCRETE	70.7	82.8	5850	377	484123	484500

Y 64.28 in  
 AY<sup>2</sup> 512151 in<sup>4</sup>  
 lc 108527 in<sup>4</sup>

S con 4830 in<sup>3</sup>  
 S top 7131 in<sup>3</sup>  
 S bot 1688 in<sup>3</sup>

27 Sept 49

CORPS OF ENGINEERS, U. S. ARMY

PAGE 23

SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY M.D. CHECKED BY \_\_\_\_\_ DATE 5/3/94

BRIDGE RATING @ 2ND CUTOFF 21.5' FROM END

DEAD LOAD STRESS

$$f_{top} = f_{bot} = \frac{N}{S} = \frac{1199.3(12)}{1309} = 10.99 \text{ ksi}$$

SUPERIMPOSED DEAD STRESS

$$f_{tenc} = \frac{184.5(12)}{(2439 \times 27)} = 0.03 \text{ ksi}$$

$$f_{top} = \frac{184.5(12)}{(3105)} = 0.71 \text{ ksi}$$

$$f_{bot} = \frac{184.5(12)}{1597} = 1.42 \text{ ksi}$$

ADJAC STRESS FOR WIDE LOAD

$$f_{tenc} = 1.2 - 0.03 = 1.17 \text{ ksi}$$

$$f_{top} = 19.8 - 10.99 - 0.71 = 8.1 \text{ ksi}$$

$$f_{bot} = 19.8 - 10.99 - 1.42 = 7.39 \text{ ksi}$$

ADJAC Y MOMENT

M: FS

$$M_{tenc} = 1.17 (4830 \times 9) / 12 = 4238 \text{ k.ft}$$

$$M_{top} = 8.1 (7131) / 12 = 4813.4 \text{ k.ft}$$

$$M_{bot} = 7.39 (1688) / 12 = 1039.5 \text{ k.ft}$$

27 Sept 49

CORPS OF ENGINEERS, U.S. ARMY

PAGE 24

SUBJECT BLACK ROCK SERVICE BRIDGECOMPUTATION BRIDGE RATING ANALYSISCOMPUTED BY M. D. CHECKED BY \_\_\_\_\_ DATE 5/8/94

RATING

INVENTOR

$$\left( \frac{1039.5}{661.7} \right) 20 = \underline{31.4T}$$

OPERATING

ALLOWED STRESS

$$27 - 10.99 - 1.42 = 14.59 K$$

ALLOWED MOMENT

$$14.59 (1638) / 12 = 2052.3 K.F.$$

RATING

OPERATING

$$\left( \frac{2052.3}{661.7} \right) 20 = \underline{62.0T}$$

SERVICE BRIDGE RATING ANALYSIS  
PLATE GIRDER COMPOSITE RATING

PROJECT: Black Rock Service Bridge  
DATE: 05/03/94  
SECTION: Second cutoff at 20.5' from end

FOR LIVE LOAD	fs top	15.3 ksi
(OPERATING)	fs bot	14.59 ksi

AVAILABLE LIVE LOAD	M conc	4238 k-ft
MOMENT	Ms top	4813 k-ft
(INVENTORY)	Ms bot	1040 k-ft

AVAILABLE LIVE LOAD	M conc	4238 k-ft
MOMENT	Ms top	9092 k-ft
(OPERATING)	Ms bot	2052 k-ft

CONTROLLING VALUES		
(INVENTORY)	M max.	1040 k-ft
(OPERATING)	M max.	2052 k-ft

# SERVICE BRIDGE RATING ANALYSIS PLATE GIRDER COMPOSITE RATING

PROJECT: Black Rock Service Bridge  
 DATE: 05/03/94  
 SECTION: Second cutoff at 20.5' from end

RATING	
INVENTORY	31.4 Tons
OPERATING	62 Tons

MOMENTS k-ft	
DEAD LOAD	1199
SUPERIMPOSED DL	185
LIVE LOAD	1085

TABULATED SECTION PROPERTIES:			
STRESS AREA	STEEL ONLY	COMPOSITE W/CREEP	COMPOSITE WO/CREEP
S concrete		2439	4830
S top flange	1309	3105	7131
S bot flange	1309	1557	1688

OTHER	
Fy STEEL	36000
f'c CONCRETE	3000
n	9
ALLOW fs INVENTORY	19800
ALLOW fs OPERATING	27000
ALLOW fc	1200
DISTRIBUTION FACTOR	0.61

DEAD LOAD STRESS	fs top	10.99 ksi
	fs bot	10.99 ksi

SUPERIMPOSED	fc conc	0.03 ksi
DEAD LOAD STRESS	fs top	0.71 ksi
	fs bot	1.42 ksi

AVAILABLE STRESSES	fc conc	1.17 ksi
FOR LIVE LOAD	fs top	8.1 ksi
(INVENTORY)	fs bot	7.39 ksi

AVAILABLE STRESSES	fc conc	1.17 ksi
--------------------	---------	----------



## **X. APPENDIX**

## FHWA STRUCTURE INVENTORY, CONDITION, & APPRAISAL RATING GUIDE

The numerical condition ratings should characterize the general condition of the entire component being rated. They should not attempt to describe localized or nominally occurring instances of deterioration or disrepair. Correct assignment of a condition rating must, therefore, consider both the severity of the deterioration or disrepair and the extent to which it is widespread throughout the component being rated.

However, in some cases, a deficiency will occur on a single element or in a single location. If that one deficiency reduces the load carrying capacity or serviceability of the component, then the element can be considered a "weak link" in the structure, and the rating of the component should be reduced accordingly.

The following general condition rating guidelines (obtained from the 1988 version of the *Coding Guide*) are to be used in the evaluation of the deck, superstructure, and substructure.

### Code    Description

N	NOT APPLICABLE
9	EXCELLENT CONDITION
8	VERY GOOD CONDITION - no problems noted.
7	GOOD CONDITION - some minor problems.
6	SATISFACTORY CONDITION - structural elements show some minor deterioration.
5	FAIR CONDITION - all primary structural elements are sound but may have minor section loss, cracking, spalling, or scour.
4	POOR CONDITION - advanced section loss, deterioration, spalling, or scour.
3	SERIOUS CONDITION - loss of section, deterioration, spalling, or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.
2	CRITICAL CONDITION - advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
1	"IMMINENT" FAILURE CONDITION - major deterioration or section loss present in critical structural components, or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put bridge back in light service.
0	FAILED CONDITION - out of service; beyond corrective action.

# STRUCTURES INSPECTION FIELD REPORT

## INVENTORY INSPECTION

city/town <b>COLEBROOK</b>		bridge dept. no.		8-structure no.		90-date inspected <b>0195</b>	
2-dist. 104-highway system		22-owner <b>COE</b>		27-year built <b>1965</b>		106-year rebuilt	
43-structure type <b>PLATE GIRDER (2 SPANS)</b>		quality control engineer <b>TOMAS G. STUOPIS, P.E. (MA # 36855)</b>					
07-facility carried <b>SERVICE ROAD TO INTAKE CONTROL TOWER</b>		team leader <b>ROBERT R. HINDMAN, P.E. (MA # 31800)</b>					
06-features intersected		team members <b>P. NAGLE, P. GROSSKAMP</b>					

<b>item 58</b> <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> <b>DECK</b> 1. Wearing Surface <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 2. Deck-Condition <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 3. Stay in Place Forms <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 4. Curbs <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 5. Median <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 6. Sidewalks <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 7. Parapet <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 8. Railing <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 9. Anti Missile Fence <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 10. Drains <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 11. Lighting Standards <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 12. Utilities <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 13. Deck Joints <span style="float: right; border: 1px solid black; padding: 2px;"><b>6</b></span> 14. Approach Settlement <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span>	<b>item 59</b> <span style="float: right; border: 1px solid black; padding: 2px;"><b>6</b></span> <b>SUPERSTRUCTURE</b> 1. Bearing Devices <span style="float: right; border: 1px solid black; padding: 2px;"><b>6</b></span> 2. Stringers <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 3. Diaphragms <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 4. Girders or Beams <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 5. Floor Beams <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 6. Trusses <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 7. Rivets or Bolts <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 8. Welds <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 9. Collision Damage <span style="float: right; border: 1px solid black; padding: 2px;"><b>8</b></span> 10. Load Deflection <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 11. Member Alignment <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 12. Load Vibration <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 13. Paint-Epoxy <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 14. Year Painted <span style="float: right; border: 1px solid black; padding: 2px;"><b>90</b></span> 15. Under Clearance _____ ft _____ in Clearance Signs <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	<b>item 60</b> <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> <b>SUBSTRUCTURE</b> 1. Abutments a-Wings <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> b-Backwall <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> c-Bridge Seats <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> d-Breastwall <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> e-Footings <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> f-Piles <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> g-Erosion <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> h-Settlement <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 2. Piers or Bents a-Caps <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> b-Column <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> c-Web <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> d-Footing <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> e-Piles <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> f-Scour <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> g-Settlement <span style="float: right; border: 1px solid black; padding: 2px;"><b>7</b></span> 3. Collision Damage <span style="float: right; border: 1px solid black; padding: 2px;"><b>8</b></span> 4. Hydraulic-Adequacy <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span>
--	--	---

<table style="width: 100%;"> <tr> <td style="text-align: center;">H</td> <td style="text-align: center;">3</td> <td style="text-align: center;">3S2</td> <td style="text-align: center;">single</td> </tr> <tr> <td>Actual Posting <input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Recommended Posting <input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>From Rating Book <input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td colspan="4">Waived Date: _____</td> </tr> <tr> <td colspan="2">SIGNS IN PLACE</td> <td colspan="2">at bridge</td> </tr> <tr> <td>Y or N</td> <td><input type="checkbox"/></td> <td>advance</td> <td><input type="checkbox"/></td> </tr> <tr> <td>LEGIBILITY</td> <td><input type="checkbox"/></td> <td></td> <td><input type="checkbox"/></td> </tr> <tr> <td>NOT APPLICABLE</td> <td><input checked="" type="checkbox"/></td> <td></td> <td></td> </tr> </table>	H	3	3S2	single	Actual Posting <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Recommended Posting <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	From Rating Book <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Waived Date: _____				SIGNS IN PLACE		at bridge		Y or N	<input type="checkbox"/>	advance	<input type="checkbox"/>	LEGIBILITY	<input type="checkbox"/>		<input type="checkbox"/>	NOT APPLICABLE	<input checked="" type="checkbox"/>			<b>Overhead Signs (attached to bridge)</b> <input type="checkbox"/> yes <input checked="" type="checkbox"/> no 1. Welds <input type="checkbox"/> 2. Bolts <input type="checkbox"/> 3. Condition <input type="checkbox"/> <b>Item 93b U/W Inspection Date:</b>
H	3	3S2	single																																		
Actual Posting <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																		
Recommended Posting <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																		
From Rating Book <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																																		
Waived Date: _____																																					
SIGNS IN PLACE		at bridge																																			
Y or N	<input type="checkbox"/>	advance	<input type="checkbox"/>																																		
LEGIBILITY	<input type="checkbox"/>		<input type="checkbox"/>																																		
NOT APPLICABLE	<input checked="" type="checkbox"/>																																				

<b>ITEM 61-channel and channel protection</b> <span style="float: right; border: 1px solid black; padding: 2px;"><b>N</b></span> 1. channel scour <input type="checkbox"/> 2. embankment erosion <input type="checkbox"/> 3. fender system <input type="checkbox"/> 4. spur dikes & jetties <input type="checkbox"/> 5. rip rap or slope paving <input type="checkbox"/> 6. effectiveness <input type="checkbox"/> 7. debris <input type="checkbox"/> 8. vegetation <input type="checkbox"/> <b>ITEM 61 U/W</b> <input type="checkbox"/>	<b>36-Traffic Safety features</b> <table style="width: 100%;"> <tr> <td style="text-align: center;">36</td> <td style="text-align: center;">condition</td> </tr> <tr> <td>1. bridge railing <input type="checkbox"/></td> <td><span style="border: 1px solid black; padding: 2px;"><b>7</b></span></td> </tr> <tr> <td>2. transitions <input type="checkbox"/></td> <td><span style="border: 1px solid black; padding: 2px;"><b>N</b></span></td> </tr> <tr> <td>3. approach guardrail <input type="checkbox"/></td> <td><span style="border: 1px solid black; padding: 2px;"><b>N</b></span></td> </tr> <tr> <td>4. guardrail terminal <input type="checkbox"/></td> <td><span style="border: 1px solid black; padding: 2px;"><b>N</b></span></td> </tr> </table>	36	condition	1. bridge railing <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>7</b></span>	2. transitions <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>	3. approach guardrail <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>	4. guardrail terminal <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>
36	condition										
1. bridge railing <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>7</b></span>										
2. transitions <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>										
3. approach guardrail <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>										
4. guardrail terminal <input type="checkbox"/>	<span style="border: 1px solid black; padding: 2px;"><b>N</b></span>										

**X=UNKNOWN**

**N=NOT APPLICABLE**

**IA=INACCESSIBLE**

# Remarks, Photos and Sketches

city/town <b>COLEBROOK</b>	bridge dept. no.	8-structure no.	90-date inspected <b>0195</b>
-------------------------------	------------------	-----------------	----------------------------------

## ACCESSABILITY:

Y/N	LIFT BUCKET	BOAT	RAILROAD FLAGMAN	INSPECTOR GO	OTHER	FOGGING	STAGING	TRAFFIC CONTROL	UNDERWATER INSPECTION	HOURS
Y				Y						

## CURB REVEAL:

10"

## PLANS?

Y/N **Y**

## SCOUR:

Y/N **N**

## RATING REPORT:

Y/N	DATE
<b>N</b>	

## RE-RATE?

Y/N	PRIORITY
<b>N</b>	H/M/L